

METHOD OF CHECK Image Quality Control Division

Customer: Vimercati East Europe

Date: 14.05.2024

Quality Responsible Customer: Sorin Ochiana

Position: Quality Manager

Quality Responsible Car Builder:

Position:

Defect (description): GAP >0.6mm between bezel and buttons

Part Name: Radio Switch 250SX

Part Number: 34356073A

Safety equipment required: NO

Action Type (ex: sorting, inspect, rework, other): Sorting with filler 0.6 mm and rework

Method of check: Filler gage 0.6mm and screwdriver

Others supplementary requirements regarding the method of check (pictures, technical design, etc.):

Modalities to identify the parts after the checks:

Others supplementary information:


Customer signature 	Car Builder signature	Image Quality Control Division Team Leader signature
--	------------------------------	---

Image Quality Control Division SRL

Tel: 0040 372 776 170; Tel: 0040 372 915 200

Fax: 0040 348 457 786

E-mail: office@imagequality.ro

